

**CONSOL ENERGY™**

Consolidation Coal Company

P.O. Box 566

Sesser, IL 62884

(618) 625-2041

August 8, 2007

Darron Haddock  
Utah Division of Oil, Gas and Mining  
Coal Program  
1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801

AUG 13 2007

Re: Emery Deep Mine Permit C/015/015  
Citation 10005

Dear Mr. Haddock:

Please consider this a request to extend the abatement deadline for the above mentioned citation until August 31, 2007. In reviewing the options to abate the citation it was discovered that the drainage map and associated culverts and ditches around the stockpile area were not constructed in the field as designed in the MRP. The ditches and additional culverts built in the field will meet the regulatory design requirements, but detailed field mapping will need to be completed. This field mapping will consist of a ground survey to determine drainage boundaries of pond 8 and all associated ditches and culverts that convey drainage from the coal stockpile and underground development waste area. Once this is complete the drainage system will be designed to handle the proper storm event, per the citation.

If you have any questions concerning this request, please call me at (618) 625-6850.

Sincerely,

John Gefferth  
Environmental Engineer

CC: Karl Houskeeper – DOGM-Price Field Office-  
Pamela Grubaugh-Littig- DOGM Salt Lake City

JAG/jag emrefuse.NOV10005.extreq.doc